



## AD Overview

Aircraft Registration  
**UP-DH601**

| 1. Description: PROPELLER HARTZELL, W/LATCH |                                                | 2. Model: HC-B3TN-3DY |              | 3. S/N: BUA33360                          |                 | 4. Manuf./Receipt: 08.06.2015 |
|---------------------------------------------|------------------------------------------------|-----------------------|--------------|-------------------------------------------|-----------------|-------------------------------|
| Document Number                             | Relevant Part / Task                           | Performed Date        | Performed at | Maintenance Action Performed              | Next Compliance |                               |
|                                             |                                                |                       |              |                                           | Interval        | Due at                        |
| CF-1981-13 Rev.0<br>08.06.1981<br>TCCA      | PROPELLERS OVERHAULED BY AERO PROPELLERS       | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-1972-08-04 Rev.0<br>04.11.1972<br>FAA    | PROPELLER BLADES (HC SB 97)                    | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-1974-14-01 Rev.0<br>22.08.1974<br>FAA    | PROPELLER BLADES (HC SB 105)                   | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-1983-08-01 Rev.2<br>11.05.2005<br>FAA    | PROPELLER ATTACHMENT BOLTS (HC SI 140A)        | 08.06.2015            | 0:00 h       | C/W AT MANUFACTURE<br>Zimex Aviation Ltd. |                 |                               |
| US-1996-15-04 Rev.0<br>29.07.1996<br>FAA    | PROPELLER BLADE SHANK (HC ASB 61-220)          | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-1996-18-14 Rev.0<br>16.10.1996<br>FAA    | PROPELLER HUB                                  | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-2003-13-17 Rev.0<br>18.07.2003<br>FAA    | PROPELLERS OVERHAULED BY T&W PROPELLER SERVICE | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-2005-14-11 Rev.0<br>17.08.2005<br>FAA    | PROPELLERS OVERHAULED BY SC PROPELLER SERVICE  | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-2005-14-12 Rev.0<br>29.07.2005<br>FAA    | PROPELLER MOUNTING BOLTS (HC ASB 61-279R4)     | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |
| US-2006-24-07 Rev.0<br>03.01.2007<br>FAA    | PROPELLERS SERVICED BY CSE AVIATION            | 08.06.2015            | 0:00 h       | Not Applicable<br>Zimex Aviation Ltd.     |                 |                               |



## AD Overview

Aircraft Registration  
**UP-DH601**

| 1. Description: PROPELLER HARTZELL, W/LATCH |                                              | 2. Model: HC-B3TN-3DY |              | 3. S/N: BUA33360                          |                 | 4. Manuf./Receipt: 08.06.2015 |  |
|---------------------------------------------|----------------------------------------------|-----------------------|--------------|-------------------------------------------|-----------------|-------------------------------|--|
| Document Number                             | Relevant Part / Task                         | Performed Date        | Performed at | Maintenance Action Performed              | Next Compliance |                               |  |
|                                             |                                              |                       |              |                                           | Interval        | Due at                        |  |
| US-2009-10-14 Rev.0<br>04.06.2009<br>FAA    | STEEL HUB TURBINE PROPELLERS (HC-ASB-61-313) | 08.06.2015            | 0:00 h       | Not Applicable<br><br>Zimex Aviation Ltd. |                 |                               |  |