

Customer: 9H-Aviation
Attn.: Charles Hergott
Address:

Phone: +41 76 733 74 84
E-Mail: c.hergott@9haviation.com

Your Contact at Zimex Aviation Ltd.:

Name: Erich Kunz
Tel.: +41 44 815 5447
Fax: +41 44 881 32 16
E-mail: erich.kunz@zimex.com

Quote: **Q26-014 - DHC6-400, MSN 925**
Reference: **10-Year Inspections and G1000 Avionic Upgrade**

Page: 1
Date: 25.02.26

Dear Charles
Please find following our cost estimate for the 10-Year Inspections Package

	Total Labour and Material
1.1 Scheduled Work - 10-Year Inspection Package	CHF 157'129.88
2.1 Additional Work / Findings	CHF 17'551.17
Total Cost Estimate - Avionic Mod per Aircraft	CHF 174'681.05

TBA = TO BE ADVISED / APR = AS PER RESULT

Terms and Conditions

- A) Prices: Prices quoted are for budgetary purpose and do not include Freight, VAT (no VAT for export), customs duties, and other applicable taxes.
Quote is based on Work performed in Altenrhein
- B) Payment terms: 50% with firm order and 50% prior work start
- C) Validity of Quote: 30 Days
- D) Parts Lead Time: 8 Weeks
- E) Shipping: N/A
- F) Ground Time: Approximately 6 Weeks for above Work Package
- G) Additional work: Any additional Work over and above this Quote will be invoiced additionally, and might extend the Ground Time. Zimex will inform the Customer of all additional Findings during work-in-process, and will request the Customer's approval for the Rectification of such Findings.
- H) Test Flights: Test Flights, Ferry Flights, Fuel, Landing Fees, and other related Costs are not included in this Quotation.
- I) Release back: Zimex Engineers are certified under EASA / TCCA.
- K) Warranty: For Labour Refer to Zimex GTC, Rev.1, 2013 <http://www.zimex.com/solutions/maintenance/>

We would be pleased, to perform this work for you.
If you have any questions or if you need additional information, please do not hesitate to contact us.

Best regards



Erich Kunz
Head of Technical Services



Daniele Cersghetti
CEO

Approved by customer:

Name: _____

Signature: _____

Date: _____

Task	ATA	Description	Remarks	Labour Mechanics CHF	Total 3. Party CHF	Total Material CHF
1.1 - Scheduled Work - 10-Year Inspection Package						
1	05	Incoming Inspection / Final Check		67.50	APR	
2	05	EMMA Inspection #7 - 18	LUMP (minimum 6 EMMA per Year)	14'850.00		723.92
3	05	Card Cal 12 Mts Inspection		1'080.00		54.60
4	05	10-Year Inspections and G1000 Avionic Upgrade		2'430.00	156.25	
5	05	Corrosion Inspection i.a.w.. PSM 1-6-5	CPCP Year 1 of 5 to 5 of 5	21'600.00		2'670.20
6	05	Card SP2-C1 - Flight Control System Inspection	Every 400 Hrs AD CF 72-06 i.a.w. SB 6/511	67.50		
7	05	Card SP2 C7 - Wing Flap and Flight Control Rod Inspection	CF-79-22, CF-80-03, SB 6/502	1'012.50		
8	05	Card SP2-C8 - Replacement of Rudder, Elevator and Aileron Primary Flight Control Cables	Every 5 Years	5'400.00		6'802.66
9	05	Card SP2-C9 - Sta 270.3 Pulley Replacement	Every 5 Years	67.50		371.78
10	05	Cards SP2-D2 - INBD Trailing Flap Inspection	Every 400 Hrs Mod 6/1556	NOT DUE YET		
11	05	Card SP2-D4 - Lwr Wing Skin & Cap Angle Inspection (Mod 6/1318)	Initial Inspection at 12'000hrs or 24'000 cycles PSM 1-6-7 Part 3, Fig 6 and 7	NOT DUE YET		
12	05	Card SP2-D6 - Lwr Wing Skin Inspection WS185	Initial Inspection at 24'000hrs or 48'000 cycles PSM 1-6-11 / SB 6/362	NOT DUE YET		
13	05	Card SP2-D7 - Lwr Wing Skin Inspection Rib 8 to 20	Initial Inspection at 24'000hrs or 48'000 cycles PSM 1-6-7 Part 3 PSM 1-6-11	NOT DUE YET		
14	05	Card SP2-D8 - Lwr Wing Fitting Insp. WS 97.5	Initial Inspection at 31'800hrs or 63'000 cycles PSM 1-6-7 Part 3 PSM 1-6-11	NOT DUE YET		
15	05	Card SP2-D9 - Wing Strut Bolt Inspection	Every 2.5 Years / 3000 Hrs	NOT DUE YET		
16	05	Card SP2-D10 - LH/RH Wing Bolt Inspection	Every 2.5 Years	NOT DUE YET		
17	05	Card SP2-D11 - LH/RH Wing Main Spar Lower Cap Angle Inspection i.a.w. SB6/492	Initial Inspection after 10 Years AD CF 87-02/1	1'080.00		295.98
18	05	Card SP2-D12 - LH/RH Wing Strut Inspection i.a.w. SB 6/474	Every 5 Years / 6000 Hrs AD CF 85-14	1'485.00		21.84
19	05	Card SP2-E3 - Horizontal Stabilizer Bracket Inspection i.a.w. SB 6/438 and 6/513	Every 8 Mts AD CF 92-04	N/A BY MOD STATUS		
20	05	Card SP2-E4 - Horizontal Stabilizer Centre Hinge Bracket Inspection i.a.w. SB 6/512	Every 1200 Hrs AD CF 92-05	N/A BY MOD STATUS		
21	05	Card SP2-E5 - Horizontal Stabilizer OUTB Hinge Inspection i.a.w. SB 6/421	Every 1200 Hrs AD CF-82-21/1	NOT DUE YET		
22	05	Card SP2 E7 / F4 - Fuselage / Stabilizer Special Inspection	Every 5 Years / 6000 Hrs SB 6/454 Part A	810.00		81.16
23	05	Card SP3 L1-L7 - Cold Weather Operations Kit Inspection	SOO 6276	135.00		
24	24	Card SP O1 - Main Battery Check	Every 6 Mts / 375 Hrs Battery failed last check -> Replace Battery	135.00		
25	24	Avionic Start Battery Capacity Check	Every 1000 Hrs	N/A BY MOD STATUS		
26	24	LH / RH RCR Bench Test	P/N: A701D TBO 3000 Hrs	NOT DUE YET		
27	25	First Aid Kit Inspection	Replace	67.50		49.14
28	25	Cockpit Seat Belt Inspection	Every 12 Mts	135.00		
29	25	Cabin Seat Belt Inspection	Every 12 Mts	675.00		
30	25	Card SP2-H1 - ELT Annual ELT Check	Every 12 Mts	202.50		
31	25	ELT Battery replacement	P/N: 452-0133 Next due 31.12.26	NOT DUE YET		

32	26	Card SP2-J5 - RH Engine Fire Extinguisher Cartridge Replacement	P/N: 601-004	INCLUDED IN CARD SP2-J6		
33	26	Card SP2-J2 - Cockpit & Cabin Fire Extinguisher inspection and weight check	Every 6 Mts	SEE SOO 6533		
34	26	Card SP2-J3 - LH / RH Engine Fire Extinguisher loop inspection	Every 6 Mts	202.50		
35	26	Card SP2-J6 - LH Engine Fire Extinguisher Overhaul	P/N: 601-004 Every 3000 Hrs / 5 Years	405.00	0.00	1'612.80
36	26	Card SP2-J6 - RH Engine Fire Extinguisher Overhaul	P/N: 601-004 Every 3000 Hrs / 5 Years	405.00	0.00	1'612.80
37	26	SOO 6533 - Installation of Halotron Hand Fire Extinguishers		270.00		4'368.00
38	27	CF-2017-20 - SB V6-0022B - Aileron Cable fouling at Fuselage Skin	Every 500 Hrs	270.00		
39	27	CF-2018-28 - SB V6/0062 STA 270.3 Pulley Inspection / Replacement		INCLUDED IN CARD SP2-C9		
40	27	CF-2020-45R1 - SB V6/0067A Rudder Pedal Torque Tube Inspection	Pre Mod 6/2496	135.00		
41	27	Inspection of Rudder Pedals for Cracking i.a.w. V6/0052	(1-844 ONLY) - N/A TO DHC-6-400 (S/N 001 - 845)	N/A BY MOD STATUS		
42	28	Airframe Fuel Hose Inspection		135.00		
43	31	Card SP2-N1 - ESIS Battery Periodic Check	Every 1000 Hrs or 3 Mts	67.50		
44	31	Card SP2-N2 - ESIS Battery Periodic Check	Every 3000 Hrs or 12 Mts Power Supply failed last check -> Replace	405.00		
45	31	Card SP2-N3 - CVR ULB Periodic Check	Every 3000 Hrs or 12 Mts	135.00		
46	31	Card SP2-N4 - FDR ULB Periodic Check	Every 3000 Hrs or 12 Mts	135.00		
47	31	Card SP2-N5 - CVR Intelligibility Check	Every 3000 Hrs or 12 Mts	270.00	1'000.00	
48	31	Card SP2-N6 - FDR Correlation Check	Every 3000 Hrs or 12 Mts	1'485.00	1'062.50	
49	31	Card SP2-N7 - ESIS Calibration Check	Every 3000 Hrs or 12 Mts	135.00		
50	31	Card SP2-N8 - CVR Function Test	Every 12 Mts	135.00		
51	31	Card SP2-N9 - ESIS Altimeter Check	Every 24 Mts	202.50		
52	31	MAU Cabinet Visual Corrosion Inspection	Pay Particular attention to the cooling Fan Area	742.50		
53	31	FDR ULB - Replace	Every 72 Mts P/N: 266-E5542-00	NOT DUE YET		
54	31	CVR ULB - Replace	Every 72 Mts P/N: 266-E5542-00	NOT DUE YET		
55	32	LH MLG INITIAL OVERHAUL	> STRIP MLG AND SEND LEG FOR O/H > NDT AXLE AND STAY STRUT > PAINT & FREIGHT CHARGES	2'970.00	1'687.50	9'720.00
56	32	RH MLG INITIAL OVERHAUL	> STRIP MLG AND SEND LEG FOR O/H > NDT AXLE AND STAY STRUT > PAINT & FREIGHT CHARGES	2'970.00	1'687.50	9'720.00
57	34	Annual Radio Check		1'080.00		
58	34	CARD SP2-L1 - Compass Swing	Every 12 Mts	135.00		
59	34	Card SP2-L2 - ADAHRS Compass Accuracy Verification	Every 12 Mts	135.00		
60	34	Card SP2-L3 - ADAHRS Altimeter Test and Pitot Static Leak Check	Every 24 Mts FAR 91.411	405.00		
61	34	Card SP2-L4 to L6 - #1 & #2 XPDR Test	Every 24 Mts FAR 91.413	270.00		
62	34	Pitot Static System Leak Check	FAR 91.411	135.00		
63	34	NAV Data Base and EGPWS Database update		270.00		TBA
64	53	[53-006] SB 6/521 - Fuselage Frame FS239 Inspection	Every 12 Mts AD CF-95-12/1	810.00		
65	54	[54-008] SB 6/509 - LH / RH Nacelle Longerons Inspection	Every 200 Hrs	NOT DUE YET		

66	57	MOD 6/1869 - Installation of Access Holes into LH/RH lower Wing Skin i.a.w. SB 6/486D	Including Paint Touch-up	16'470.00	1'875.00	4'914.00
67	57	CF-2020-05 - Aileron Rib Inspection i.a.w. SB V6/0066A	Due at 10 Years	405.00		
68	61	LH/RH Propeller Inspection / Lubrication		0.00		
69	61	LH Propeller Overhaul	P/N: HC-B3TN-3DY Every 3000 Hrs or 60 Mts	877.50		10'587.94
70	61	RH Propeller Overhaul	P/N: HC-B3TN-3DY Every 3000 Hrs or 60 Mts	877.50		10'589.16
71	71	CARD SP2 G1.1 - LH / RH Engine Mounts Inspection (Nacelle)		NOT DUE YET		
72	71	LH / RH Engine Fluid Hose Inspection	Every 1000 Hrs / 60 Mts	270.00		
73	71	Card SP2 G2 - LH / RH Engine Vibration Insulator Inspection	Every 3000 Hrs	NOT DUE YET		
74	72	LH / RH Engine Compressor Recovery Wash		202.50	0.00	143.51
75	72	LH / RH Engine Borescope Inspection	Every 400 Hrs	NOT DUE YET		
76	72	LH / RH Engine Hot Section Inspection	Every 2000 Hrs	NOT DUE YET		
77	73	LH / RH Engine Fuel Nozzle Inspection	Every 400 Hrs	NOT DUE YET		
78	73	LH / RH Engine Fuel Pump Inlet Screen Inspection	Every 600 Hrs	INCLUDED IN EMMA CHECK		
79	75	LH / RH Engine Bleed Valve Inspection	Every 600 Hrs	NOT DUE YET		
80	76	LH / RH Engine FCU Rod Inspection	CF-2021-42 - SB V60063A (D5) - Every 125 Hrs	67.50		
81	79	LH / RH Engine Chip Detector Bridging Check	Every 600 Hrs / 12 MTHS	135.00		1.64
82	79	LH / RH Engine Scavenge Pump Inlet Screen Inspection	Every 1000 Hrs	NOT DUE YET		
83	79	LH / RH Engine Oil Filter - Replace	P/N: 7579431AM Every 1000 Hrs	NOT DUE YET		
84	79	LH / RH Engine Oil Cooler Overhaul	P/N: C6SC1141-3 Every 3000 Hrs	NOT DUE YET		
85	80	LH / RH Starter Generator Brush Check	Every 375 Hrs	NOT DUE YET		
86	80	LH / RH Starter Generator Overhaul	P/N: 23048-046 Every 1500 Hrs	NOT DUE YET		
Labour & Material Breakdown				85'320.00	7'468.75	64'341.13

TBA = TO BE ADVISED / APR = AS PER RESULT

CHF 157'129.88

Task	ATA	Description	Remarks	Labour Mechanics CHF	Total 3. Party CHF	Total Material CHF
2.1 - Additional Work / Findings						
1	11	CHANGE REGISTRATION ON FUSELAGE & WINGS AND MANUFACTURE FIREPROOF IDENTIFICATION PLATE	UP-DH601 to new Registration	675.00	6'437.50	
2	24.02	MAIN BATTERY FAILED CAP TEST	BATTER NEED TO BE REPLACED NOTE: TASK ON HOLD	135.00		4'782.77
3	24.03	ESIS BATTERY FAILED TEST	ESIS BATTERY NEED TO BE SENT FOR SERVICING / REPAIR NOTE: TASK ON HOLD	135.00		4'023.40
4	25	10-Year Inspections and G1000 Avionic Upgrade	UP-DH601 to new Registration	270.00		
5	34	REPROGRAM TRANSPONDER	UP-DH601 to new Registration UPLOAD OF NEW SETTING FILE	405.00	687.50	0.00
Labour & Material Breakdown				1'620.00	7'125.00	8'806.17

TBA = TO BE ADVISED / APR = AS PER RESULT

CHF 17'551.17