



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1968-05 Rev.0 15.04.1968 TCCA	AILERON MASS BALANCE WEIGHT (SB 6/100) (MSN 1-115)	08.06.2015	0:00 h 0 F	C/W - Post Mod 6/1104 Zimex Aviation Ltd.		
CF-1968-09 Rev.0 01.07.1968 TCCA	LH ELEVATOR TRIM TAB (SB 6/65, 6/68, 6/69) (MSN 1-105) (PRE MOD 6/1120, 6/1135, 6/1142)	08.06.2015	0:00 h 0 F	C/W - Post Mod 6/1120, 6/1135, 6/1142 Zimex Aviation Ltd.		
CF-1968-18 Rev.0 01.01.1968 TCCA	SUPERSEDED BY CF-1969-20	01.01.1968	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-01 Rev.0 01.01.1969 TCCA	SUPERSEDED BY CF-1969-05	01.01.1969	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-04 Rev.0 01.01.1969 TCCA	SUPERSEDED BY CF-1976-08	01.01.1969	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-05 Rev.0 01.01.1969 TCCA	SUPERSEDED BY CF-1976-08	01.01.1969	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-07 Rev.0 01.01.1969 TCCA	SUPERSEDED BY CF-1969-09	01.01.1969	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-09 Rev.0 01.01.1969 TCCA	SUPERSEDED BY CF-1972-06R5	01.01.1969	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1969-20 Rev.0 01.01.1969 TCCA	WING STRUT JO-BOLTS (SB 6/166B) (MSN 1-170)	08.06.2015	0:00 h 0 F	By Wing Strut P/N Not Applicable Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-1970-07 Rev.1 31.12.1970 TCCA	ENGINE CONTROL CABLES PT6A-20, PT6A-6B	31.12.1970	0:00 h 0 F	BY ENGINE TYPE Not Applicable Zimex Aviation Ltd.			
CF-1970-10 Rev.0 15.01.1971 TCCA	CIRCUIT WIRES PROTECTION (SB 6/245A) (MSN 6-289)	08.06.2015	0:00 h 0 F	Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.			
CF-1971-02 Rev.0 01.01.1971 TCCA	SUPERSEDED BY CF-1971-12	01.01.1971	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			
CF-1971-07 Rev.0 18.06.1971 TCCA	FUEL STARVATION (SB 6/269A) (MSN 1-299) (MOD 6/1406)	08.06.2015	0:00 h 0 F	Post Mod 6/1406 Zimex Aviation Ltd.			
CF-1971-11 Rev.0 01.09.1971 TCCA	J.B. SYSTEMS AIR CONDITIONER (SB 6/280) (MSN 1-299)	08.06.2015	0:00 h 0 F	NO AIRCON INSTALLED Not Applicable Zimex Aviation Ltd.			
CF-1971-12 Rev.0 30.11.1971 TCCA	LOSS OF A.C. POWER (SB 6/263E) (MSN 6-289)	08.06.2015	0:00 h 0 F	Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.			
CF-1972-06 Rev.5 06.07.2018 TCCA	FLIGHT CONTROL SYSTEM INSP / MOD - PART I (SB 6/180F) (MSN 1-378)	08.06.2015	0:00 h 0 F	Not Applicable Zimex Aviation Ltd.			
CF-1972-06 Rev.5 06.07.2018 TCCA	FLIGHT CONTROL SYSTEM INSP / MOD - PART II (SB 6/181B) (MSN 2-222)	08.06.2015	0:00 h 0 F	Not Applicable Zimex Aviation Ltd.			



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1972-06 Rev.5 06.07.2018 TCCA	US-2022-10-07 - FLIGHT CONTROL SYSTEM INSP / MOD - PART III (SB 6/511)	14.04.2023	59:18 h 0 F	CARD SP2 C1 W/O: 430055 Zimex Aviation Ltd.	400:00 h	459:18 h
CF-1973-03 Rev.1 01.06.1991 TCCA	WING REAR SPAR INSPECTION (SB 6/295D) (MSN 1-330)	08.06.2015	0:00 h 0 F	C/W - Post Mod 6/1301 Zimex Aviation Ltd.		
CF-1973-04 Rev.0 18.06.1973 TCCA	PROPELLER AUTOFEATHER SYSTEM (SB 6/297C) (MSN 6-230)	08.06.2015	0:00 h 0 F	By A/C S/N - Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.		
CF-1973-06 Rev.2 06.01.1995 TCCA	OVERHEAD ENGINE CONTROL QUADRANTS (SB 6/298D) (MSN 1-420)	08.06.2015	0:00 h 0 F	C/W - Post Mod 6/1895 Zimex Aviation Ltd.		
CF-1973-09 Rev.0 29.06.1973 TCCA	PROPELLER AUTOFEATHER SYSTEM (SB 6/299A) (MSN 231-290)	08.06.2015	0:00 h 0 F	By A/C S/N - Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.		
CF-1973-11 Rev.0 30.06.1973 TCCA	FLOAT TO CHASSIS BOLTS (SB 6/296) (UP TO FLOAT S/N 271)	08.06.2015	0:00 h 0 F	No Floats installed. Not Applicable Zimex Aviation Ltd.		
CF-1973-12 Rev.0 01.02.1974 TCCA	SIDE SEAT RAIL ATTACHMENT (SB 6/302A) (MSN 136-368)	08.06.2015	0:00 h 0 F	No inward facing seats installed. Not Applicable Zimex Aviation Ltd.		
CF-1974-04 Rev.0 01.09.1974 TCCA	HORIZ STAB REAR SPAR (SB 6/310A) (MSN 1-393)	08.06.2015	0:00 h 0 F	BY A/C S/N Not Applicable Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-1974-07 Rev.0 06.01.1975 TCCA	RH AILERON CONTROL CABLE DAMAGE PRECLUDE (SB 6/304C) (MSN 1-135)	08.06.2015	0:00 h 0 F	BY A/C S/N Not Applicable Zimex Aviation Ltd.			
CF-1975-03 Rev.0 01.01.1975 TCCA	SUPERSEDED BY CF-1975-14	01.01.1975	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			
CF-1975-06 Rev.0 30.08.1975 TCCA	SLOW BLOW FUSES TYPE 313 (SB 6/263D) (MSN 231-427)	08.06.2015	0:00 h 0 F	Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.			
CF-1975-11 Rev.0 01.12.1975 TCCA	REVERSE CURRENT RELAY (SB 6/338) (MSN ALL) (PRE MOD 6/1585)	08.06.2015	0:00 h 0 F	Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.			
CF-1975-14 Rev.0 01.02.1976 TCCA	FLOAT WATER COMPARTMENT	08.06.2015	0:00 h 0 F	NO FLOATS INSTALLED Not Applicable Zimex Aviation Ltd.			
CF-1976-04 Rev.0 01.01.1976 TCCA	SUPERSEDED BY CF-1976-21	01.01.1976	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			
CF-1976-08 Rev.0 01.01.1976 TCCA	SUPERSEDED BY CF-85-12R3	01.01.1976	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			
CF-1976-18 Rev.0 01.01.1976 TCCA	SUPERSEDED BY CF-77-05R1	01.01.1976	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1976-21 Rev.0 03.01.1977 TCCA	WING TIP LIGHTNING PROTECTION (SB 6/318A) (MSN 1-469)	08.06.2015	0:00 h 0 F	By A/C S/N & Post Mod 6/1513 Not Applicable Zimex Aviation Ltd.		
CF-1977-05 Rev.1 01.06.1991 TCCA	ELEVATOR CTRL HOUSING ASSY CRACKING (SB 6/348D) (MSN 1-507)	08.06.2015	0:00 h 0 F	C/W - Post Mod 6/1594 Zimex Aviation Ltd.		
CF-1977-08 Rev.0 30.09.1977 TCCA	REVERSE CURRENT RELAYS (SB 6/353A) (MSN 1-530)	08.06.2015	0:00 h 0 F	Post Mod 6/2028 Not Applicable Zimex Aviation Ltd.		
CF-1978-17 Rev.1 01.06.1991 TCCA	FUSELAGE SIDE FRAME CRACKING (SB 6/371B) (MSN 1-411)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.		
CF-1979-02 Rev.0 15.02.1979 TCCA	ELEVATOR CONTROL SYSTEM (SB 6/379B) (MSN 331-563)	08.06.2015	0:00 h 0 F	BY MOD STATUS Not Applicable Zimex Aviation Ltd.		
CF-1979-03 Rev.0 01.01.1979 TCCA	SUPERSEDED BY CF-1979-04	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1979-04 Rev.0 01.01.1979 TCCA	SUPERSEDED BY CF-1979-15	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1979-15 Rev.0 01.01.1979 TCCA	SUPERSEDED BY CF-1979-18	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1979-18 Rev.0 01.01.1979 TCCA	SUPERSEDED BY CF-1979-22R2	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1979-22 Rev.2 09.07.1993 TCCA	CONTROL RODS INSPECTION (SB 6/502) (MSN ALL)	25.10.2024	59:48 h 23 F	CARD SP2 C7 W/O: 440295 Zimex Aviation Ltd.	2'400:00 h 24.00 M	2'459:48 h 25.10.2026
CF-1979-24 Rev.0 17.12.1979 TCCA	BETA RANGE THROTTLE ARMING SWITCH (SB 6/309C) (MSN 1-450)	08.06.2015	0:00 h 0 F	BY A/C S/N Not Applicable Zimex Aviation Ltd.		
CF-1980-01 Rev.0 01.02.1980 TCCA	FLOAT STRUT FAILURE (SB 6/330B, 6/357B)	08.06.2015	0:00 h 0 F	NO FLOATS INSTALLED Not Applicable Zimex Aviation Ltd.		
CF-1980-03 Rev.4 09.07.1993 TCCA	FLIGHT CONTROL RODS (SB 6/390G) (MSN 1-685)	25.10.2024	59:48 h 23 F	CARD SP2 C7 W/O: 440295 Zimex Aviation Ltd.	2'400:00 h 24.00 M	2'459:48 h 25.10.2026
CF-1980-06 Rev.0 21.03.1980 TCCA	MLG Y-JOINT WELD (SB 6/380C, V6/0016B) (MSN 1-603)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.		
CF-1980-21 Rev.0 01.01.1980 TCCA	SUPERSEDED BY CF-1980-22	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.		
CF-1980-22 Rev.0 10.11.1980 TCCA	PROP REVERSING LINKAGE INTERCONNECT	08.06.2015	0:00 h 0 F	BY ENGINE TYPE Not Applicable Zimex Aviation Ltd.		
CF-1981-05 Rev.0 27.02.1981 TCCA	COCKPIT ROOF ELECTRICAL WIRING INSPECTION (SB 6/401C)	08.06.2015	0:00 h 0 F	BY MOD STATUS Not Applicable Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-1981-07 Rev.4 25.04.1994 TCCA	ENGINE NACELLE LOWER LONGERONS (SB 6/509A)	08.06.2015	0:00 h 0 F	s/s by CF-2019-02 Zimex Aviation Ltd.			
CF-1982-20 Rev.0 16.08.1992 TCCA	WINDSHIELD WASHER / DE-ICER SYSTEM (SB 6/422B) (MSN 1-810)	08.06.2015	0:00 h 0 F	SYSTEM NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
CF-1982-21 Rev.1 01.06.1991 TCCA	ELEVATOR ROOT RIB INSPECTION (SB 6/399F) (MSN 1-810) (PRE MOD 6/1769)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.			
CF-1983-11 Rev.1 20.05.1994 TCCA	ELEVATOR HINGE ARM ASSY (SB 6/228) (MSN 1-285)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.			
CF-1983-25 Rev.2 05.05.1986 TCCA	CABIN UTILITY SEATS (SB 6/447D) (MSN 1 & SUB)	08.06.2015	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
CF-1983-32 Rev.0 21.11.1983 TCCA	FUEL VENT FLAME ARRESTOR (SB 6/211B) (MSN 6-310)	08.06.2015	0:00 h 0 F	BY MOD STATUS Not Applicable Zimex Aviation Ltd.			
CF-1984-03 Rev.0 22.02.1984 TCCA	NOSE GEAR STEERING CABLES (SB 6/453) (MSN 1-800)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.			
CF-1985-12 Rev.3 01.06.1991 TCCA	CRACKING OF WING TO FUSELAGE ADAPTOR FITTINGS (SB 6/476C, 6/500D)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.			
CF-1985-14 Rev.0 25.11.1985 TCCA	WING STRUT CORROSION (SB 6/474A) (MSN ALL)	28.10.2021	58:54 h 21 F	CARD SP2 D12 W/O: 410079 Zimex Aviation Ltd.	6'000:00 h 60.00 M	6'058:54 h 28.10.2026	



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1987-02 Rev.1 01.06.1991 TCCA	WING SPAR LOWER CAP ANGLE INSPECTION (SB 6/492B, 6/486D) (MSN ALL)	08.06.2015	0:00 h 0 F	INITIAL INSP.: 10 YEARS (DOM) Zimex Aviation Ltd.	120.00 M	08.06.2025
CF-1990-01 Rev.0 31.01.1990 TCCA	FLIGHT CONTROL GUST LOCKS (SB6/508A) (MSN 1-690)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.		
CF-1990-10 Rev.0 14.05.1990 TCCA	ELEVATOR QUADRANT PUSHROD INSPECTION (MSN ALL)	08.06.2015	0:00 h 0 F	NEW RODS INSTALLED Not Applicable Zimex Aviation Ltd.		
CF-1991-30 Rev.0 20.09.1991 TCCA	WING STRUTS CHAFING - UPPER FAIRING (SB 6/342A) (MSN 1-474)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.		
CF-1992-04 Rev.0 09.03.1992 TCCA	TAILPLANE ATTACHMENT INSPECTION (SB 6/438D, 6/513A) (MSN 3-820)	08.06.2015	0:00 h 0 F	By A/C S/N Not Applicable Zimex Aviation Ltd.		
CF-1992-05 Rev.0 20.03.1992 TCCA	CENTRE HINGE BRACKET INSPECTION (SB 6/512) (MSN ALL)	08.06.2015	0:00 h 0 F	CARD SP2 E4 Zimex Aviation Ltd.	1'200:00 h	1'200:00 h
CF-1993-25 Rev.0 22.11.1993 TCCA	CORROSION OF RIVETS IN WING LEADING EDGE (SB 6/517) (MSN ALL)	08.06.2015	0:00 h 0 F	C/W AT MANUFACTURE Zimex Aviation Ltd.		
CF-1994-12 Rev.1 28.05.1999 TCCA	CORROSION PREVENTION AND CONTROL PROGRAM PSM 1-6-5 PART 3	08.06.2015	0:00 h 0 F	SEE CF--99-11 Zimex Aviation Ltd.		
CF-1995-12 Rev.0 16.08.1995 TCCA	SKIN CRACKING FS 239.88 (SB 6/521C) (MSN ALL)	08.06.2015	0:00 h 0 F	NEW PARTS INSTALLED Not Applicable Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-1996-15 Rev.0 01.01.1996 TCCA	SUPERSEDED BY CF-2000-14	08.06.2015	0:00 h 0 F	CANCELLED Zimex Aviation Ltd.			
CF-1999-11 Rev.0 28.05.1999 TCCA	CORROSION TASKS - REPETITIVE INSPECTIONS (PSM 1-6-5) (MSN ALL)	08.06.2015	0:00 h 0 F	INITIAL: 120 MONTHS Zimex Aviation Ltd.	120.00 M	08.06.2025	
CF-2000-14 Rev.0 07.07.2000 TCCA	SERVICE LIFE LIMIT INFORMATION (PSM 1-6-11 REV. 5) (MSN ALL)	08.06.2015	0:00 h 0 F	NEW PARTS INSTALLED Not Applicable Zimex Aviation Ltd.			
CF-2002-40 Rev.0 25.10.2002 TCCA	WING SPAR STRUT LUG INSPECTION (SB 6/525A) (MSN 1-230)	08.06.2015	0:00 h 0 F	BY AIRCRAFT S/N Not Applicable Zimex Aviation Ltd.			
CF-2007-31 Rev.0 17.12.2007 TCCA	FRONT SPAR ADAPTER FITTING INSPECTION (SB 6/540, 6/541, 6/542) (MSN ALL)	08.06.2015	0:00 h 0 F	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			
CF-2017-20 Rev.0 21.06.2017 TCCA	AILERON CABLES FOULING AT FUSELAGE SKIN INSPECTION (SB V6/0022B) (MSN: ALL)	28.10.2021	299:06 h 0 F	REPETITIVE W/O: 410079 Zimex Aviation Ltd.	500:00 h	799:06 h	
CF-2018-07 Rev.0 09.03.2018 TCCA	US-2022-07-14 - SB V6/0044B CORROSION OF FUEL SYSTEM COMPONENTS (MSN 845-957 OPERATING ON FLOATS)	08.06.2015	0:00 h 0 F	NO FLOAT OPERATION Not Applicable Zimex Aviation Ltd.			
CF-2018-28 Rev.0 29.10.2018 TCCA	SB V6/0062 WORN ELEVATOR CABLES AT STA 270.3 PULLEYS	28.10.2021	58:54 h 21 F	REPETITIVE W/O: 410079 Zimex Aviation Ltd.	60.00 M	28.10.2026	



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-2019-02 Rev.0 23.01.2019 TCCA	US-2022-03-04 - SB V6/0068 TIME LIMITS / MAINTENANCE CHECKS - AIRWORTHINESS LIMITATIONS - IMPLEMENTATION	31.05.2019	57:36 h 16 F	COMPLIED WITH Zimex Aviation Ltd.			
CF-2020-05 Rev.0 27.03.2020 TCCA	US-2022-11-09 - SB V6/0066A AILERON RIB INSPECTION	08.06.2015	0:00 h 0 F	Zimex Aviation Ltd.	16'000:00 h 32'000 F 120.00 M	16'000:00 h 32'000 F 08.06.2025	
CF-2020-45 Rev.1 16.04.2021 TCCA	US-2022-10-03 - SB V6/0067A LOOSE RUDDER PEDAL TORQUE TUBE QUADRANT RIVETED CONNECTION	28.10.2021	58:54 h 21 F	COMPLIED WITH W/O: 410079 Zimex Aviation Ltd.			
CF-2021-42 Rev.0 26.11.2021 TCCA	US-2022-11-12 - SB V6/0063A (D6) - LH / RH ENGINE BINDING OF THE FCU PUSH ROD END BEARINGS INSPECTION (MOD 6/2347)	08.06.2015	0:00 h 0 F	REPETITIVE Zimex Aviation Ltd.	1'500:00 h	1'500:00 h	
CF-2021-42 Rev.0 26.11.2021 TCCA	US-2022-11-12 - SB V6/0063A (D5)- LH / RH ENGINE BINDING OF THE FCU PUSH ROD END BEARINGS (POST MOD 6/2347)	28.10.2021	58:54 h 0 F	REPETITIVE W/O: 410079 Zimex Aviation Ltd.	125:00 h	183:54 h	
CF-2024-14 Rev.0 29.05.2024 TCCA	INDICATING / RECORDING SYSTEM, NAVIGATION (RAD ALT INTERFERENCE WITH 5G C-BAND)	29.05.2024	0:00 h 0 F	BY AIRSPACE Not Applicable Zimex Aviation Ltd.			
EU-2009-0278 Rev.0 22.12.2009 EASA	SICLI (MAIP) PORTABLE HALON 1211 FIRE EXTINGUISHERS - IDENTIFICATION / REPLACEMENT	22.12.2009	0:00 h 0 F	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			
EU-2019-0235 Rev.0 20.09.2019 EASA	C406 AND G406 EMERGENCY LOCATOR TRANSMITTERS	20.09.2019	0:00 h 0 F	ELT NEVER INSTALLED ON HELICOPTER Not Applicable Zimex Aviation Ltd.			



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
US-1998-25-02 Rev.0 22.12.1998 FAA	ASB 78A - BFGOODRICH AVIONICS SYSTEMS SKYWATCH SKY 497 TOP-MOUNTED ANTENNA - AFM AMENDMENT	08.06.2015	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
US-2005-01-19 Rev.0 23.02.2005 FAA	GTX 33, GTX 33D, GTX 330 AND GTX 330D MODE S XPDR	08.06.2015	0:00 h 0 F	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			
US-2005-18-20 Rev.0 14.10.2005 FAA	GOODRICH DE-ICING SYSTEMS "FASTPROP" PROPELLER DEICERS	08.06.2015	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
US-2005-25-08 Rev.0 23.01.2006 FAA	ADC-2000 AIR DATA COMPUTER REPLACEMENT	08.06.2015	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
US-2006-16-18 Rev.1 18.07.2008 FAA	SB 3400-01 - SANDEL AVIONICS / ST3400 TAWS / RMI PLACARD INST., AFM REV., SOFTWARE UPDATE	18.07.2008	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
US-2015-10-51 Rev.0 01.07.2015 FAA	AVIDYNE INTEGRATED FLIGHT DISPLAYS - LATERAL DEVIATIONS / OPERATIONAL LIMIT	01.07.2015	0:00 h 0 F	NOT INSTALLED Not Applicable Zimex Aviation Ltd.			
US-2017-16-01 Rev.0 24.10.2017 FAA	AMERI-KING CORP. AK-450 & AK-451 ELT REPETITIVE INSPECTION	24.10.2017	0:00 h 0 F	BY ELT TYPE Not Applicable Zimex Aviation Ltd.			



AD Overview

Aircraft Registration
UP-DH601

1. Description: DHC-6 TWIN OTTER		2. Model: DHC-6-400		3. S/N: 925		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
US-2021-07-13 Rev.0 25.03.2021 FAA	PACIFIC SCIENTIFIC SEATBELTS INSPECTION / REPLACEMENT (SB 25-1111432)	25.03.2021	0:00 h 0 F	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			
US-2024-26-02 Rev.0 18.12.2024 FAA	PACIFIC SCIENTIFIC SEATBELTS INSPECTION / REPLACEMENT (SB 25-1111432)	13.12.2024	0:00 h 0 F	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			