



AD Overview

Aircraft Registration
UP-DH601

1. Description: PROPELLER HARTZELL, W/LATCH		2. Model: HC-B3TN-3DY		3. S/N: BUA33359		4. Manuf./Receipt: 08.06.2015
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance	
					Interval	Due at
CF-1981-13 Rev.0 08.06.1981 TCCA	PROPELLERS OVERHAULED BY AERO PROPELLERS	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-1972-08-04 Rev.0 04.11.1972 FAA	PROPELLER BLADES (HC SB 97)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-1974-14-01 Rev.0 22.08.1974 FAA	PROPELLER BLADES (HC SB 105)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-1983-08-01 Rev.2 11.05.2005 FAA	PROPELLER ATTACHMENT BOLTS (HC SI 140A)	08.06.2015	0:00 h	C/W AT MANUFACTURE Zimex Aviation Ltd.		
US-1996-15-04 Rev.0 29.07.1996 FAA	PROPELLER BLADE SHANK (HC ASB 61-220)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-1996-18-14 Rev.0 16.10.1996 FAA	PROPELLER HUB	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-2003-13-17 Rev.0 18.07.2003 FAA	PROPELLERS OVERHAULED BY T&W PROPELLER SERVICE	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-2005-14-11 Rev.0 17.08.2005 FAA	PROPELLERS OVERHAULED BY SC PROPELLER SERVICE	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-2005-14-12 Rev.0 29.07.2005 FAA	PROPELLER MOUNTING BOLTS (HC ASB 61-279R4)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		
US-2006-24-07 Rev.0 03.01.2007 FAA	PROPELLERS SERVICED BY CSE AVIATION	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.		



AD Overview

Aircraft Registration
UP-DH601

1. Description: PROPELLER HARTZELL, W/LATCH		2. Model: HC-B3TN-3DY		3. S/N: BUA33359		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
US-2009-10-14 Rev.0 04.06.2009 FAA	STEEL HUB TURBINE PROPELLERS (HC-ASB-61-313)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			