



AD Overview

Aircraft Registration
UP-DH601

1. Description: ENGINE		2. Model: PT6A-34		3. S/N: PCE-RB0886		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
CF-1978-03 Rev.0 28.02.1978 TCCA	MODIFICATIONS POWER TURBINE DISC (SB 1217, 1220, 1248)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-1996-24 Rev.1 13.06.2008 TCCA	US-97-04-12 - COMPRESSOR BLEED VALVE COVER ASSY INSPECTION	08.06.2015	0:00 h	CANCELLED Zimex Aviation Ltd.			
CF-1998-41 Rev.0 31.12.1998 TCCA	SB 1430R6 INSPECTION OF TURBINE EXHAUST DUCT	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-1999-23 Rev.0 15.10.1999 TCCA	COMPRESSOR BLEED OFF VALVE COTTER PIN WEAR (PT6A-25C & PT6A-114A)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-2002-47 Rev.0 18.11.2002 TCCA	US-2002-23-13 - INSPECTION OF TURBINE EXHAUST DUCT (SB 1610R2, SB 12173)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-2013-33 Rev.1 28.11.2013 TCCA	US-2014-11-05 - SUPERSEDED BY CF-2014-33 (SB A1427)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-2014-33 Rev.0 16.10.2014 TCCA	US-2014-11-05 - POWER TURBINE CONTAINMENT RING FAILURE (SB A1427R4, SB 12076R3)	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
CF-2019-30 Rev.1 31.12.2019 TCCA	US-2022-08-13 - COMPRESSOR TURBINE (CT) BLADE FRACTURE DUE TO NON-CONFORMING CT VANE INSTALLATION	08.06.2015	0:00 h	Not Applicable Zimex Aviation Ltd.			
US-1975-06-01 Rev.0 01.04.1977 FAA	GEARBOX DETERIORATION (SB 1138, 1216, 1220)	08.06.2015	0:00 h	C/W AT MANUFACTURE Zimex Aviation Ltd.			
US-1975-11-04 Rev.0 20.05.1975 FAA	REDUCTION GEARBOX ENGINE DISTRESS (SB 1216, 1220)	08.06.2015	0:00 h	BY PART NUMBER Not Applicable Zimex Aviation Ltd.			



AD Overview

Aircraft Registration
UP-DH601

1. Description: ENGINE		2. Model: PT6A-34		3. S/N: PCE-RB0886		4. Manuf./Receipt: 08.06.2015	
Document Number	Relevant Part / Task	Performed Date	Performed at	Maintenance Action Performed	Next Compliance		
					Interval	Due at	
US-1980-08-12 Rev.0 18.04.1980 FAA	SB 1316 R1 - FUEL PUMP DRIVE COUPLING SPLINES	08.06.2015	0:00 h	C/W AT MANUFACTURE Zimex Aviation Ltd.			
US-1990-12-05 Rev.0 30.05.1990 FAA	ENGINE OVERHAUL	08.06.2015	0:00 h	BY ENGINE SN Not Applicable Zimex Aviation Ltd.			
US-1992-15-11 Rev.0 17.08.1992 FAA	COMPRESSOR DELIVERY LINE (P3) FILTER ASSEMBLY	08.06.2015	0:00 h	C/W AT MANUFACTURE Zimex Aviation Ltd.			
US-2011-20-51 Rev.0 01.11.2011 FAA	FIRST STAGE REDUCTION SUN GEARS PMA TAATI	08.06.2015	0:00 h	BY P/N AND S/N Not Applicable Zimex Aviation Ltd.			
US-2011-25-12 Rev.0 28.12.2011 FAA	FIRST STAGE REDUCTION SUN GEARS PMA TAATI	08.06.2015	0:00 h	BY PN AND SN Not Applicable Zimex Aviation Ltd.			